

# Wear Resistance

## GF65 Application

Application	Housing
Material	PPS (Fortron) GF65
Cavity	4
Machine	TR20EH2
Note	Measuring wear




Result:

Installed 4 machines.

Measurement of wear after 2150,000 shot, as a result, three machines show the signs of no wear, but one detects a little sign of wear.

**Maintenance Cost for Components**



**1/8**